## TO BE FILLED BY THE INSPECTING OFFICER

4_	3.	
	Name of School	: Mount Guide International School
2.	Name of the Officer	: Assistant Engineer Prakash Babu M
	Location	: Kariyad
4.	Period for which the certificate issued	:2024-25 01/6/24 to 31/5/25
5.	Types of building	: R.C.C
		1)6.50x6.50x3.70m,6 class room,in GF
		2)7.50x6.50x3.70m 2 Rooms.in GF
		3)10.00x5.00x3.70m 1Room in GF
6.	Nature of defect if any	
	a) Foundation and basement	:4)6.50x6.50x3.70m,6 Class Room in Ist Floor/ Buildin
		5)10.00x5.00x3.70m 1 Room in Ist Floor / No:4/29
	b) Super Structure	: 6)7.50x6.50x3.70m 2 Rooms in Ist Floor
		7)6.50x6.50x3.70m 6 Class rooms in IIndFloor
	c) Doors and windows	: 8)7.50x6.5x3.70m 2Rooms in IInd Floor
		9)10.00x5.00x3.70m I Room in II <sup>nd</sup> Floor
		400000 7000 070 000
	d) Wood work wrought and put	up:10)8.00x5.00x3.70m,9 Class room in GF Building
		11)8.00x5.00x3.70m,12 Class room in FF ↑ No:4/509
	e) Roof	:
	f)Flooring	
	g)Miscellaneous	
	Any major defects notice which	
,	will render building unsafe in any	y .
1	manner	: Nil
8.	Whether maintenance work have	e
	been done properly.	: Yes
9.	Whether the structure is sound f	or
	Conducting	: Structure is Sound for conducting classes in normal wind and weather.
N	ote: 1. The stability of the structu	re should be examined also with reference to the altitude
	intensity of wind exposure	
	2. Any additional observation	n if deemed necessary for the certificate may be furnished
	separately with the certific	
		1 1
Certificate that the School was inspected by on 235 20 and found to be fit to conduct		
cla	sses for the period from	24 to 31/5/2025t
		* Office

Place: Panoor

Signature

Designation AKASHBABU M ASSISTANT ENGINEER

LID & EW PANOOR MUNICIPALITY