

**1970319/25-26**  
**TO BE FILLED BY THE INSPECTING OFFICER**  
**(Asst.Executive Engineer)**

Name of the school : MOUNT GUIDE INTERNATIONAL SCHOOL

1. Name of the Officer : SUBHEESH T

2. Location : Kariyad

3. Period for the Certificate is issued : 2025-2026

4. Types of building : RCC

Building No:30/89

6.50 x 6.50 x 3.70m, 6 Class room in GF

7.50 x 6.50 x 3.70m, 2 Room in GF

10.00 x 5.00 x 3.70m, 1 Room in GF

6.50 x 6.50 x 3.70m, 6 Class room in 1<sup>st</sup> Floor:

10.00 x 5.00 x 3.70m, 1 Room in 1<sup>st</sup> Floor

7.50 x 6.50 x 3.70m, 2 Room in 1<sup>st</sup> Floor

6.50 x 6.50 x 3.70m, 6 Class room in 11<sup>nd</sup> Floor

7.50 x 6.50 x 3.70m 2 Room in 11<sup>nd</sup> Floor

10.00 x 5.00 x 3.70m, 1 Room in 11<sup>nd</sup> Floor

Building No:30/90

8.00 x 5.00 x 3.70m, 9 Class room in GF

8.00 x 5.00 x 3.70m, 12 Class room in FF

5. Nature of defect if any

a) Foundation and basement : Nil

b) Superstructure : Nil

c) Doors and windows : Nil

d) Wood work wrought and put up : Nil

e) Roof : Nil

f) Flooring : Nil

g) Miscellaneous(Cracks if any) : Nil

6. Any Major defects notices which will Render the building unsafe if any Manner : Nil

7 Whether maintenance work have been Done properly : Yes


8 Whether the structure is sound or not for conducting Classes : Yes. The structure is fit for conducting classes under normal weather and wind condition

Note: 1.The stability of the structure should be examined also with reference to location altitude intensity of wind exposure to flood etc.

2.Any additional observation if deemed necessary for the certificate may be Furnished separately with the Certificate.

Certified that the school was inspected by me on 18-06-2025 and found to be fit to conduct classes for the period for the reason stated above.

Place :Panoor  
Date :18-06-2025



Signature

Assistant Engineer  
ISO(EW) D, Panoor Municipality  
Panoor P. O. Kannur Dist. 670 692